Lichfield to Wednesbury

Technical Annex



WALSALL METROPOLITAN BOROUGH COUNCIL

Table 1 shows the percentage of the road network that has been subject to planned programme of capital maintenance.

Table 1: Carriageway Condition

Road No	Road Name	Condition	Road Length/Sections	% Road subject to Treatment
A461	Lichfield Rd; Bescot Rd	Good	9.057km / 15 sections	A461 resurfaced, 6 schemes delivered. 35.5% of KRN route was treated
A4148	Wallows Ln; Bescot Rd; Broadway West; Pleck Rd	Good	11.261km / 39 sections	A4148 resurfaced, 7 schemes delivered. 16.5% of KRN route was treated.
			Total: 20 319km / 54 sections	Total: 52%

Total: 20.318km / 54 sections Total: 52%

Table 2: Footway Condition

Road No	Road Name	Condition	Road Length/Sections	% Road subject to Treatment
A4148	Day St	Good	15.154km / 39 sections	A4148 resurfaced, 1 scheme delivered. 0.3% of KRN route was treated.
A461	Bescot Rd	Good	15.158km / 15 sections	A461 Resurfaced, 1 scheme delivered. 2.3% of KRN route was treated.
			Tatal, 70 740lana / 54 anations	Tatal: 0.60/

Total: 30.312km / 54 sections Total: 2.6%

SANDWELL METROPOLITAN BOROUGH COUNCIL

The carriageway across this route is in a good and safe condition. Over the past five years there has been a systematic planned programme of capital maintenance carried out on the A461. Table 3 shows the percentage of the road network that has been subject to planned programme of capital maintenance.

Table 3: Carriageway Condition

Road No	Road Name	Condition	Road Length/Sections	% Road subject to Treatment
A461	Dudley Street	Good	0.673km / 2 sections	0%
A461	High Bullen	Good	1.062km / 5 sections	37% resurfaced in 2016
A461	Walsall Street	Good	0.617km / 2 sections	8% resurfaced in 2013
A461	Wood Green Road	Good	1.810km / 3 sections	0%

The footway across the Lichfield to Wednesbury route is in a generally fair and safe condition. There is no systematic planned programme of capital maintenance carried out on the A461. Any defective footway repairs are identified and carried out on a reactive basis.

Table 4: Footway Condition

Road No	Road Name	Condition	Road Length/Sections	% Road subject to Treatment
A461	Dudley Street	Good	0.673km	0%
A461	High Bullen	Good	1.062km	0%
A461	Walsall Street	Good	0.617km	0%
A461	Wood Green Road	Good	1.810km	0%

Table 5: Structures

Road No.	Structure Number	Structure Name	Road Name	Condition	BCI Av	BCI Crit
A461	135	Wood Green Underpass	Wood Green Road	Fair	76	81